APPENDIX D – PHOTO LOG				



UXO Technicians conducting Visual Survey with Analog Instruments operations



UXO Technicians conducting Visual Survey with Analog Instruments operations within Stony Creek



UXO Technician along the slope of Second Mountain



UXO Technicians conducting Analog Instruments operations



UXO Technicians conducting Visual Survey with Analog Instruments operations along the Second Mountain



UXO Technicians conducting Visual Survey with Analog Instruments operations along the ridge line of Second Mountain



50-foot by 50-foot grid layout for DGM activities



Geophysical Specialist conducting a grid sweep



DGM equipment



Technician placing metal seed with grid for QA/QC purposes



Geophysical Specialist explaining DGN equipment to USACE Representative



Geophysical Specialist conducting post-operations QA check for DGM equipment



Geophysical Specialist conducting land surveying operation



Geophysical Specialist conducting land surveying operation



Survey contractor establishing benchmarks for DGM grids



Geophysical Specialist conducting land surveying operation



Geophysical Specialist establishing benchmarks for DGM grids



UXO Technician investigating possible munitions during mag & dig operation



UXO Technicians investigating possible munitions during mag & dig operation



UXO Technicians and Geophysical Specialist placing QA/QC seeds in the geophysical system verification test strips.



UXO Technicians assembling material to construct demolitions structure for blow-in-place (BIP) operations



UXO Technicians assembling material to construct demolitions structure for blow-in-place (BIP) operations on the ridge line of Second Mountain







































































